



Enter Setup



Restore Default Settings

Scanner Settings



Continuous Mode

Interface Settings : Keyboard Wedge



PCAT (German)



0x03



Validate



Update